

Industrial Waste Inspection Request

Requested by D. Penfield Date 5/27/82 Permit No. 1354
 To: For: Initial Date Copy Desired Acct. No. 1189526
 Plan Evaluation Checking HCR 6/1
 Surcharge Checking PC 5/27/82
 Section Head Approval K 6/2
 or Supv. Engr. Insp. Approval
 Processing Process & Forward PC 6/9
 Insp. Supv. Note & Forward M 6/7
 Inspector: Rands DK 6/9
 Priority: ASAP
 SOON

Doc. No. DAU25ROUTINELogin: 6-21-02 DMAbstract complete: Data Extracted:

Company Name Fried R. Pippy, Inc. Enviro Doc. 104
 Address 12471 E. Washington Blvd., Whittier, Ca 90602
 Contact John R. Pippy Position V.P. Phone 6295-7501

Type of Inspection: Routine Permit Evaluation Surcharge Evaluation
 Complaint Violation Enforcement Treatment Plant
 Follow-up Other

Reason for Request Company closing no I.W. Please
Verify.
 Doc. No.:
 Login:
 Abstract complete:
 Data Extracted:

Inspection Results Company installed a cooling tower to recirculate
the cooling water used in their vinyl department. This unit does about
a year ago. The current plant is for a small metal working operation
that was discontinued about 1 year ago. John Pippy stated that
there is not present in the plant any live operations. The old never
operated pump is not being used. Thus that company is now a
non-discharger but they still have an open I.W. registration. The

Return to: Initial Date Attachments simplest way to handle them
 Insp. Supv. M 6/21 would be to keep their permit for the
 Processing PC 6/22 open connection in force and to exempt
 Requestor them from paying surcharge by giving them our
 Standard C. M.G.Y. exemption.

Copies as indicated above.

Industrial Waste Inspection Request

Requested by J. Pangle Date 5/27/82 Permit No. 1354
To: For: Initial Date Copy Desired Acct. No. PLF9576
Plan Evaluation Checking PCR 6/1 District 18
Surcharge Checking PC 5/27/82 Fiscal Year 1981-82
Section Head Approval K 6/2 Priority:
or Supv. Engr. Insp. Approval _____ ASAP _____
Processing Process & Forward PC 6/2 SOON _____
Insp. Supv. Note & Forward M 6/7 ROUTINE _____
Inspector: Rands 6/2 6/7

Company Name Fried R. Peppy, Inc.
Address 12471 E. Washington Blvd., Whittier, Ca 90602
Contact John R. Peppy Position V.P. Phone 629-8-7501

Type of Inspection: Routine Permit Evaluation Surcharge Evaluation
 Complaint Violation Enforcement Treatment Plant
 Follow-up Other

Reason for Request Company claims no I.W. Please specify.

Inspection Results Company installed a cooling tower to re-circulate the cooling water used in their copper smelting. This was done about a year ago. The current is for a small metal recycling operation that was discontinued about 1 year ago. John Peppy stated that they do not plan to re-circulate their operation. The old copper contaminated pump is not being used. Thus that company is now a non-discharger but they will have an open fire connection. The

Return to: Initial Date Attachments Simplest way to handle them would be to keep their permit for the open connection in force and to exempt them from paying surcharge by giving them our standard 2 1/2% extension.
Insp. Supv. M 6/21
Processing PC 6/22
Requestor _____
Copies as indicated above.

Industrial Waste Inspection Request

Requested by J. Pangilinan Date 5/27/82 Permit No. 1354

To:	For:	Initial	Date	Copy Desired	Acct. No.	District	Fiscal Year
Plan Evaluation	Checking	HCR	6/1	✓	148576	18	1981-82
Surcharge	Checking	WC	5/27/82				
Section Head	Approval	K	6/2				
or Supv. Engr. Insp.	Approval						
Processing	Process & Forward	RJ	6/3	✓			
Insp. Supv.	Note & Forward	M	6/7				
Inspector: <u>Rands</u>		JK	6/9				

Company Name First R. Bimby, Inc.
 Address 12471 E Washington Blvd., Whittier, Ca 90602
 Contact John R. Bimby Position V.P. Phone 695-9101

Type of Inspection: Routine Permit Evaluation Surcharge Evaluation

Complaint Violation Enforcement Treatment Plant
 Follow-up Other

Reason for Request Company claims no I.W. Please verify.

Inspection Results Company claimed a cooling tower is receiving 1000 cubic water used in their water treatment. This was done about a year ago. The present is for a small metal working operation that was discontinued about 1 year ago. John Bimby stated that they do not have a legitimate business operation. The oil sewer connected pump is not being used. Thus that company is having non-discharge but they still have an open fire connection. The

Return to: Initial Date Attachments Simplest way to handle them would be to keep their permit for the open connection in force and to exempt them from paying surcharge by giving them our standard 1 day exemption.

Insp. Supv. M 6/21

Processing RJ 6/22

Requestor _____

Copies as indicated above.

PLAN EVALUATION FORM

LOG No. 01354 B-1

ACCT. No. 1489376

COMPANY NAME

FRED R. RIPPY, INC.

TG 55-D6
 CSD DATE RECEIVED AVG. FLOW GPD CONNECTION FEE
 18 08 13 82 0 FILE No.
 PAGE 1 of 1

INITIAL & DATE	STATUS/REMARKS	Class I	II <input checked="" type="checkbox"/>	Existing <input checked="" type="checkbox"/>	Critical <input type="checkbox"/>
		New Construction <input type="checkbox"/>	Addendum <input type="checkbox"/>	Non-critical <input checked="" type="checkbox"/>	
	<ul style="list-style-type: none"> - Metal Stamping. SIC No. 3469 - Inspection by Doug Rands on 6-16-82 - Verified that company is not discharging any IW. - Original permitted flow was 1177 gpd for a degreaser and a pickling tank. - Company has a 2-compartment interceptor, 3'x4'x3' (approx. 270 gal). - No outside drains. 				
8-17-82 LJ	<ul style="list-style-type: none"> - Surcharge check: - Recommend for approval 				